

# Work Order ID 72257

Friday, July 22, 2011 10:03:15 AM

Page 1

Item ID: D4025-1

Revision ID:

Item Name: Fuel Quantity Sender

Start Date: 7/21/2011 Start Qty: 1.00

Required Date: 7/22/2011 Req'd Qty: 1.00

Reference: RMA RA111172

Approvals: Process Plan: *W*

QC:

Date:

Date:

Tooling:

SPC (Y/N):

Date:

Date:

Run Start

Stop

Sequence ID/  
Work Center ID

Operation  
Description

Set Up/  
Run Hours

Tool ID

Tool #

Plan  
Code

Accept  
Qty

Reject  
Qty

Reject  
Number

Insp.  
Stamp

Draw Nbr

Revision Nbr

D4025

A

100

0.00

QC

Quality Control

Memo

INSPECT RA111172  
(D4025-1 WAS PART OF ORIGINAL PART RETURNED, AND GOOD TO  
RETURN TO STOCK)

*Sublog/03*

0.00

110

0.00

Packaging

Packaging

Memo

IDENTIFY & STK USING NEW B/N

*141A*

*11/8/14 SP R*

0.00

120

QC21- Final Inspection - Work Order Release

0.00

QC

Quality Control

Memo

0.00

*CK 11/08/04*

*11-08-9*

# Picklist Print

Friday, July 22, 2011 10:03:13 AM

Page 1

Work Order ID: 72257



Parent Item: D4025-1

Parent Item Name: Fuel Quantity Sender

Start Date: 7/21/2011

Required Date: 7/22/2011

Start Qty: 1.00

Required Qty: 1.00

Comments: IPP rev A 10.02.02 new issue Prelim EC verified by:DD IPP Rev:B  
10.05.17 as per ECN10-562 DD verf:EC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
---------------------------------	------------------------	---------------	-------------	---------------------	------------------	-----------------	--------------------	----------------	-------------	--------------	---------------	----------------	--------

D4025-1		Manufactured	No				Each	3.0000		1			
---------	--	--------------	----	--	--	--	------	--------	--	---	--	--	--



Fuel Quantity Sender



B62139

Location

Loc Qty

Loc Code

ST142

3

69502

3

8 w/los/03

# **RA 111172**

Received @ Dart July 19<sup>th</sup>, 2011  
Inspected July 19<sup>th</sup>, 2011

## **Instructions for Dart Tank**

- Create work order to test tank for leaks
- Tank was returned with cap and fuel sender assembled
- Has leak on to same face but opposite end of the cap

## **Instructions for returned D4025-1 B62139**

- D4025-1 was never installed
- To be returned back in to stock with a new BATCH #
- Need a work order for this

## **Instructions for the JAC tank**

- Create work order to test tank for leaks
- Has leak on to same face but opposite end of the cap
- Tank has no Cap but has the fuel sender

**Date:** 10/24/16

**Attach Copy of DHS Return Authorization #: 00436**

Reason for Return:

- 200000 DAZ-1: NOISE AT TAIL. LOWEST FUEL LOAD ON  
- 300000 TAIL AT 120000 CIRCLES. 100000 IS 120000 - TAIL FOR 100

<b>Prepaid</b>	<b>Collect</b>
----------------	----------------

H:\FORMS\Quality Assurance\approved QA\CR rev J